

Autologic Quick Test Report

VIN	SALLSAA649A198565
Manufacturer	Land Rover
VEHICLE	Range Rover Sport L320 V6 2.7 Diesel with cDPF
Year	2009
Country/Area	UK, EU & ROW
KM Reading	171371km (106 421mils)
Autologic information	Autologic Serial Number A023690 Land Rover Software Version 3.92.17 Main Software Version 6.10.6
Time/Date	19:50 29/09/2019

11 MODULES WITH FAULTS

10 MODULES NOT RESPONDING

ENGINE CONTROL MODULE

2 Faults Present

- U0416-00** INVALID DATA RECEIVED FROM VEHICLE DYNAMICS CONTROL MODULE.
No sub type information.
- P1623-00** IMMOBILIZER CODE WORD/IDENTIFICATION NUMBER WRITE FAILURE.
No sub type information.
-

ALL TERRAIN CONTROL MODULE

1 Fault present

- U0416-94** INVALID DATA RECEIVED FROM VEHICLE DYNAMICS CONTROL MODULE.
Unexpected operation.
-

TRANSMISSION CONTROL MODULE

1 Fault present

- U0155-87** LOST COMMUNICATION WITH INSTRUMENT CLUSTER CONTROL MODULE.
Missing a message.
-

TRANSFER CASE CONTROL MODULE

1 Fault present

- U0155-87** LOST COMMUNICATION WITH INSTRUMENT CLUSTER CONTROL MODULE.
Missing a message.
-

VEHICLE DYNAMICS CONTROL MODULE

1 Fault present

U0155-87 LOST COMMUNICATION WITH INSTRUMENT CLUSTER CONTROL MODULE.
Missing a message.

RIDE LEVEL CONTROL MODULE

1 Fault present

U0416-86 INVALID DATA RECEIVED FROM VEHICLE DYNAMICS CONTROL MODULE.
Signal is invalid.

PARKING BRAKE CONTROL MODULE

2 Faults Present

U0101-87 LOST COMMUNICATION WITH TRANSMISSION CONTROL MODULE.
Missing a message.

C1A55-64 IGNITION SWITCH INPUT CIRCUIT.
Signal plausibility failure.

STEERING ANGLE SENSOR MODULE

1 Fault present

U0122-87 LOST COMMUNICATION WITH VEHICLE DYNAMICS CONTROL MODULE.
Missing a message.

INSTRUMENT CLUSTER

3 Faults Present

U0010-88 MEDIUM SPEED CAN COMMUNICATION BUS.
Bus is off.

U0132-87 LOST COMMUNICATION WITH RIDE LEVEL CONTROL MODULE.
Missing a message.

U0159-87 LOST COMMUNICATION WITH PARKING ASSIST CONTROL MODULE.
Missing a message.

PARKING AID CONTROL MODULE

3 Faults Present

U0155-87 LOST COMMUNICATION WITH INSTRUMENT CLUSTER CONTROL MODULE.
Missing a message.

U0140-87 LOST COMMUNICATION WITH BODY CONTROL MODULE.
Missing a message.

U0300-55 INTERNAL CONTROL MODULE SOFTWARE INCOMPATIBILITY.
Is not configured.

CELL PHONE MODULE

1 Fault present

U3003-17 BATTERY VOLTAGE.

Circuit voltage above threshold.

MODULES NOT FITTED OR NOT COMMUNICATING

SPEED CONTROL MODULE
REAR DIFFERENTIAL CONTROL MODULE
FRONT LIGHTING CONTROL MODULE
BODY CONTROL MODULE
AUXILIARY HEATER CONTROL MODULE
ACTIVE ROLL CONTROL MODULE
TYRE PRESSURE MONITOR MODULE
SATELLITE AUDIO UNIT MODULE
REAR ENTERTAINMENT CONTROL MODULE
TELEVISION MODULE

MODULES WITH NO FAULTS STORED

RESTRAINTS CONTROL MODULE
AUDIO FRONT CONTROL MODULE
HVAC CONTROL MODULE
FRONT ENTERTAINMENT CONTROL MODULE
AUDIO AMPLIFIER MODULE
TRAFFIC MESSAGE CONTROL MODULE

Diagnostic Report compiled by Autologic Diagnostics

www.autologic.com