
ISTA system version: 4.15.33.17444 Data version: R4.15.33 Programming data: 4.15.32

VIN: WBAFW110X0DU19170 Vehicle: 5/F10/SEDAN/520d/N47/AUTO/ECE/LL/2011/03

Int.lev.works: F010-11-03-511 Int.lev.(cur.): F010-17-11-520 Int.lev.(tar.): F010-18-11-520

Mileage: 109520 km

Code	Description	Mileage	Existent	Class
S 0235	No communication possible with: Electronic transmission control	109520	yes	
S 0398	Power management, battery condition: Battery faulty or worn out	109520	yes	
242400	Preheater plug, cylinder 2, activation: Open circuit	109520	yes	
242800	Preheater plug, cylinder 3, activation: Open circuit	109520	yes	
242C00	Preheater plug, cylinder 4, activation: Open circuit	109520	yes	
4809C1	EMF: Brake cannot be mechanically applied	109520	No	
B7F68B	KOMBI: Gangpositions-, Schaltpunktanzeige abgeschaltet (Umsetzungsfehler)	109520	No	
C9440A	ACSM, PT-CAN: communication fault	109520	No	
CD040A	ZGM, PT-CAN: communication fault	109520	yes	
CD9467	No message (status, seat belt contact, seat occupancy, 0x297), receiver DME/DDE, transmitter ACSM	109520	No	Information
CD94DE	Botschaft (DIENSTE-ID2=140 OBD Sensor Diagnosestatus, 0x580-0x5FF, FA): Botschaft von diversen Sende-Steuergeräten (Kombi, ...) ausgefallen	109520	yes	Information
D016DC	Message (display, driving dynamics, 97.1.2) missing, receiver ICM, transmitter instrument panel	109520	No	Information
D016F5	No message (seat belt buckle contact / seat occupancy, 275.6.8), receiver ICM, transmitter ACSM	109520	No	Information
D01B00	Message (request, hydraulic function, 64.1.2) missing, receiver ICM, transmitter parking brake	109520	No	Information
D356F5	No message (status, seat belt, contact, seat occupancy, 275.6.8), receiver DSC, transmitter ACSM	109520	No	Information
D35B00	No message (request, hydraulic function, 100.1.2), receiver DSC, transmitter EMF	109520	No	Information
D3840A	EMF, PT-CAN: Communication fault	109520	No	Information
D40D1E	Ultrasonic sensor for PMA, front left side: Communication failure to control unit PMA	109520	yes	
D40D1F	Ultrasonic sensor for PMA, front right side: Communication failure to control unit PMA	109520	yes	
E0840A	GWS, PT-CAN: communication fault	109520	No	
E1040A	Instrument panel: FA CAN: Communication fault	109520	No	
E11465	Instrument panel: CAN: Communication fault	109520	No	Information