

Detected errors report

Workshop informations

Scan date 16/06/2019 12:00:02

Car information

VIN	---
Car type	
Reg. Plate no.	
Customer	
ECU No	3Q0907572C
Name	J428 ACC BOSCH MQB
Coding	2A00600251FFC428949C8045
Software	0196

Errors found

1229(\$0004CD):09 (U101400) Control module incorrectly coded Break / short to ground. Lamp OFF Status unknowm