

Windows Based VAG/VAS Emulator Running on Windows Vista x86
Version: Release 20.4.0
www.Ross-Tech.com

Diagnostic Trouble Code Report
Wednesday, 15, April, 2020, 15:35:46:34725

[illegible]

37221 - Position Sensor for Coolant Flow Control Valve
P2B61 00 [167] - Stuck Closed
MIL ON - Not Confirmed - Tested Since Memory Clear
Freeze Frame:
 Fault Status: 00000001
 Fault Priority: 2
 Fault Frequency: 1
 Mileage: 40153 km
 Date: 2020.04.12
 Time: 01:19:58

Engine speed: 0.00 /min
Normed load value: 0.0 %
Vehicle speed: 0 km/h
Coolant temperature: 23 °C
Intake air temperature: 16 °C
Ambient air pressure: 1020 mbar
Voltage terminal 30: 12.740 V
Unlearning counter according OBD: 40
Engine temp. mangmt. actuator: actual value of angle: 76.60 %
Engine temp. management actuator: raw value: 3489.4 mV
Voltage terminal 30: 12.740 V

Readiness: 1110 0001