

Vakgarage Blaak
Beneden Oostdijk 18
Den Bommel, 3258 AB
0187611317

Technician:

Pre Scan Vehicle System Report

2013 Renault Captur 1.2L Petrol (H5FT)

VIN

Odometer

License

03 June, 2021 3:42 PM

CODE SCAN RESULTS

Systems Analyzed: 15



Systems w/ Codes

Engine

DTCC101 | Lost communication with Transmission Control module
DTCC121 | Lost Communication With Anti-Lock Brake System (ABS) Control Module
DTC1525 | Cruise Control/Speed Limiter Deactivation

Transmission

DF077 | Gearbox Input No 1 Speed Sensor Circuit
DF078 | Gearbox Input No 2 Speed Sensor Circuit
DF027 | Battery Voltage out of Range
DF105 | Left Hand Front Wheel Speed Multiplex Information Missing
DF104 | Right Hand Front Wheel Speed Multiplex Information Missing
DF015 | Computer Malfunction Clear fault and retest
DF098 | Multiplexed Network Error
DF106 | Right Hand Rear Wheel Speed Multiplex Information Missing
DF107 | Left Hand Rear Wheel Speed Multiplex Information Missing
DF101 | Brake Pedal Position Multiplex No Signal to UCH

Antilock Brakes

DTC C101 | Automatic Transmission Multiplexed Signal Error
DTC C100 | Invalid Injection Multiplex Signal
DTC C073 | Multiplex Network Error
DTC F003 | Computer Voltage High/Low

Airbag

DF011 | Warning Light Circuit Error

DF025 | Multiplexed Network Error

Body System

DF014 | Starter Relay Circuit Malfunction

Climate Control

DF020 | Computer supply voltage

Instrument Panel

DF011 | Multiplex Network Error

DF001 | Oil Level Sensor Circuit Malfunction

DF005 | Seat Belt Warning Light Circuit Malfunction

Power Steering

DF009 | Multiplex Error From ABS Detected

DF008 | Multiplex Error From Injection Detected

DF013 | Multiplex Network Failure

DF014 | ABS Multiplex Network Information Missing

DF006 | Steering Wheel Angle Sensor Calibration

Switching Protection Unit

DF0003 | Computer Main Supply Voltage Out Of Range

DF0012 | Ignition Relay Control Circuit Malfunction

DF0017 | Auxiliary Protection Circuit Circuit No 5 Malfunction

DF0034 | Battery Replacement required

DF0047 | Battery Voltage Sensor Out Of Range

DF0057 | Battery Voltage out of Range

DF0058 | Battery Voltage out of Range

DF0059 | Battery Voltage out of Range

Tire Pressure Monitor

DF014 | Starter Relay Circuit Malfunction

Telematic Control Unit

DTC 93E2 | CAN - V Fault

DTC 93E1 | CAN - M Fault

DTC 93D9 | USB Connectivity

Hands Free Module

DTCA052 | Steering Column Lock Protection

DTCA053 | Steering Column Lock +APC Circuit



Systems w/o Codes

Park Distance Control
Radio
Multimedia Interface
OBDII Codes (\$03)
OBDII Permanent Codes (\$0A)

READINESS MONITORS

✓ Complete

Misfire
EGR/VVT
Catalyst
Oxygen Sensor

● Not Complete

Fuel System
Comprehensive Component

