

Vakgarage Blaak
Beneden Oostdijk 18
Den Bommel, 3258 AB
0187611317

Technician:

Pre Scan

Vehicle System Report

2017 Volkswagen Transporter 2.0L TDI-CP (CXHA)

VIN WV1ZZZ7HZHH172824
Odometer 105,620
License

04 October, 2021 4:33 PM

CODE SCAN RESULTS

Systems Analyzed: 15

Systems w/ Codes

01-Engine Management

U014600 Lost Communication With Gateway "A"
P056800 Cruise Control Set Signal
P20EE00 SCR NOx Catalyst Efficiency Below Threshold Bank 1

02-Transmission

U112100 Databus Missing Message

09-Central Electronics

03021 Local databus 3 Electrical Problem In Circuit - Intermittent
01426 Control Unit In Steering Wheel - E221 Not A Plausible Signal - Intermittent

Systems w/o Codes

03-Brake Electronics

04-Steering Angle Sensor

08-Airco

10-Park Assist II

15-Airbag - SRS

17-Instrument Cluster

19-Diagnostic Data Interface-Gateway

25-Immobilizer

55-Level Control Xenon Lights
5F-Information Control Unit
61-Battery Regulation
69-Elec Trailer Module
OBDII Codes (\$03)
OBDII Permanent Codes (\$0A)

READINESS MONITORS

✓ Complete

Fuel System
Comprehensive Component
EGR/VVT
NMHC Catalyst
NOx Aftertreatment
Boost Pressure System
Exhaust Gas Sensor
PM Filter

● Not Complete

