

Vehicle Diagnostic Report

The Report is created by **LAUNCH X-431**

Repair Shop

Shop Name: autobedrijf van Benthum

Address:stationsweg 44 Boxmeer boxmeer

Zip Code:5831 CR

Telephone:0485572226

Email:info@autobedrijfvanbenthum.nl

SN:989510014615

Test Time:2023-02-11 03:21:42

Technician Name:J-P Van Benthum



Vehicle Information

Year:2015

Make:Citroen

Model:C4 PICASSO (B78)

VIN:VF73E5GZTFJ609910

Odometer:95235 km

Vehicle Software Version:V41.80

Diagnostic Application Version:V7.00.009

Diagnostic path: > C4 PICASSO (B78) > System Selection > Engine System > MED17_4_4



DTC

DTC	Description	State
P0606	Engine Management ECU. Internal Fault	Permanent Fault
P1337	Combustion Misfiring (Impact On Catalytic Converter) .Cylinder 1	Permanent Fault
P1338	Combustion Misfiring (Impact On Catalytic Converter) .Cylinder 2	Permanent Fault
P1336	Combustion Misfiring (Impact On Catalytic Converter) .Cylinder Undetermined	Permanent Fault